

Product Change Notification

PRECISION POTENTIOMETERS

October 17, 2018

Improved Packaging Material for Certain Bourns® Precision Potentiometers

Plastic Blister Trays

The packaging material for various precision potentiometer models will be changing from preform cardboard to plastic blister trays. As a result, minimum order quantities (MOQs) and multiples (Mults) will be affected. A complete listing of part numbers and new MOQs/Mults is shown on the following pages.

This change in packaging is being implemented for better product support in transit, and to reduce the potential for products to be damaged during shipment. There are no changes to the actual product.

New Blister Tray

FROM
Cardboard Tray
25 pieces per Tray



TO
Blister Tray
10 Pieces per Tray



Implementation dates are as follows:

*Date that manufacturing of products with existing packaging will cease: **November 30, 2018***

*Date that deliveries of products with new packaging will begin: **January 1, 2019***

If you have any questions or need additional information, please feel free to contact [Customer Service/ Inside Sales](#).

Users should verify that the described changes will not impact the performance of the product in their specific applications.

SC1837

Improved Packaging Material for Certain Bourns® Precision Potentiometers - Plastic Blister Trays

October 17, 2018

Page 2 of 10

Affected Part Numbers

Part Number	Current MOQ	Mult	New MOQ	Mult
3540S-1-101L	100	25	100	10
3540S-1-102L	100	25	100	10
3540S-1-103L	100	25	100	10
3540S-1-104L	100	25	100	10
3540S-1-153L	100	25	100	10
3540S-1-201L	100	25	100	10
3540S-1-202L	100	25	100	10
3540S-1-203L	100	25	100	10
3540S-1-252L	100	25	100	10
3540S-1-501L	100	25	100	10
3540S-1-502L	100	25	100	10
3540S-1-503L	100	25	100	10
3540S-16-103L	125	5	120	10
3540S-16-203L	125	5	120	10
3540S-16-502L	125	5	120	10
3540S-40-102L	125	5	120	10
3540S-64-102L	25	5	20	10
3540S-64-103L	25	5	20	10
3540S-80-501L	125	5	120	10
3540S-82-102TL	125	5	120	10
3540S-82-103TL	125	5	120	10
3540S-82-104TL	125	5	120	10
3540S-82-201TL	125	5	120	10
3540S-82-202TL	125	5	120	10
3540S-82-203TL	125	5	120	10

Part Number	Current MOQ	Mult	New MOQ	Mult
3540S-82-501TL	125	5	120	10
3540S-82-502TL	125	5	120	10
3540S-82-503TL	125	5	120	10
3540S-91-101L	100	25	100	10
3540S-91-102L	100	25	100	10
3540S-91-103L	100	25	100	10
3540S-91-201L	100	25	100	10
3540S-91-501L	100	25	100	10
3540S-91-502L	100	25	100	10
3540S-446-203L	125	25	120	10
3540S-446-502L	125	25	120	10
3540S-621-502L	50	1	50	10
3540S-626-502L	125	5	120	10
3540S-720-202L	100	25	100	10
3540S-722-103L	125	5	120	10
3540S-734-501L	125	5	120	10
3540S-739-102L	125	5	120	10
3540S-739-103L	125	5	120	10
3540S-743-502L	125	5	120	10
3540S-762-502L	100	5	100	10
3540S-763-103L	100	5	100	10
3540S-764-502L	100	5	100	10
3540S-765-103L	100	5	100	10
3540S-BAG-103L	0	0	210	10
3540S-BAH-103L	125	5	120	10

Improved Packaging Material for Certain Bourns® Precision Potentiometers - Plastic Blister Trays

October 17, 2018

Page 3 of 10

Affected Part Numbers (Continued)

Part Number	Current MOQ	Mult	New MOQ	Mult
3541H-1-102L	100	25	100	10
3541H-1-103L	100	25	100	10
3541H-1-104L	100	25	100	10
3541H-1-202L	100	25	100	10
3541H-1-203L	100	25	100	10
3541H-1-502L	100	25	100	10
3541H-1-503L	100	25	100	10
3541H-433-102L	125	5	120	10
3541H-476-103L	50	5	50	10
3541H-477-103L	50	5	50	10
3541H-481-102L	125	5	120	10
3541H-482-102L	125	5	120	10
3541H-482-103L	125	5	120	10
3541H-482-502L	125	5	120	10
3541H-483-102L	125	5	120	10
3541H-483-103L	125	5	120	10
3541H-483-202L	125	5	120	10
3541H-483-203L	125	5	120	10
3541H-484-202L	125	5	120	10
3541H-484-502L	125	5	120	10
3541H-485-103L	125	5	120	10

Part Number	Current MOQ	Mult	New MOQ	Mult
3541H-486-103L	125	5	120	10
3541H-498-502L	125	5	120	10
3541H-509-502L	500	25	210	10
3541H-518-501L	125	5	120	10
3541H-519-102L	125	5	120	10
3541H-520-502L	100	25	100	10
3541H-521-103L	125	5	120	10
3541H-522-103L	100	25	100	10
3541H-523-502L	125	5	120	10
3541H-525-102L	125	5	120	10
3541H-526-502L	125	5	120	10
3541H-601-103L	100	25	100	10
3541H-602-102L	500	500	210	10
3541H-766-102L	500	500	210	10
3541H-BAJ-103L	125	5	120	10
3541H-BSJ-103L	125	5	120	10
3541H-BWG-103L	125	5	120	10
3541H-40-102L	125	5	120	10
3541H-40-502L	125	5	120	10
3541H-91-103L	100	25	100	10

Part Number	Current MOQ	Mult	New MOQ	Mult
3543S-1-101L	100	25	100	10
3543S-1-102L	100	25	100	10
3543S-1-103L	100	25	100	10
3543S-1-202L	100	25	100	10
3543S-1-203L	100	25	100	10
3543S-1-502L	100	25	100	10
3543S-1-503L	100	25	100	10
3543H-40-102L	125	5	120	10
3543S-16-203L	125	5	120	10
3543S-82-102TL	125	5	120	10
3543S-82-103TL	125	5	120	10
3543S-82-202TL	125	5	120	10
3543S-82-501TL	125	5	120	10

Part Number	Current MOQ	Mult	New MOQ	Mult
3543S-82-502TL	125	5	120	10
3543S-91-103L	125	5	120	10
3543S-91-501L	125	5	120	10
3543H-685-103L	125	5	120	10
3543H-BWH-502L	100	25	100	10
3543S-423-502L	125	5	120	10
3543S-424-103L	125	5	120	10
3543S-671-103L	125	5	120	10
3543S-671-502L	125	5	120	10
3543S-678-102L	125	5	120	10
3543S-682-202L	125	5	120	10
3543S-683-203L	125	5	120	10

Improved Packaging Material for Certain Bourns® Precision Potentiometers - Plastic Blister Trays

October 17, 2018

Page 4 of 10

Affected Part Numbers (Continued)

Part Number	Current MOQ	Mult	New MOQ	Mult
3545S-1-101L	100	25	100	10
3545S-1-102L	100	25	100	10
3545S-1-103L	100	25	100	10
3545S-1-202L	100	25	100	10
3545S-1-203L	100	25	100	10
3545S-1-501L	100	25	100	10
3545S-1-502L	100	25	100	10
3545H-40-102L	125	25	120	10
3545S-64-102L	25	5	20	10
3545S-82-102TL	125	5	120	10
3545S-82-103TL	125	5	120	10
3545S-82-202TL	125	5	120	10
3545S-82-203TL	125	5	120	10
3545S-82-500TL	125	5	120	10
3545S-82-502TL	125	5	120	10
3545S-82-503TL	125	5	120	10

Part Number	Current MOQ	Mult	New MOQ	Mult
3545S-91-102L	125	5	120	10
3545S-91-103L	125	5	120	10
3545S-91-202L	125	5	120	10
3545H-429-501L	100	25	100	10
3545H-430-103L	100	50	100	10
3545H-431-102L	100	25	100	10
3545H-432-502L	100	50	100	10
3545H-433-103L	100	50	100	10
3545H-434-103L	100	25	100	10
3545H-435-501L	100	50	100	10
3545H-545-103L	100	50	100	10
3545H-BXU-102L	100	5	100	10
3545H-BYD-103L	50	50	50	10
3545S-415-103L	50	5	50	10
3545S-418-103L	125	5	120	10
3545S-418-502L	125	5	120	10

Part Number	Current MOQ	Mult	New MOQ	Mult
3547H-1AA-102A	50	25	50	10
3547H-1AA-103A	50	25	50	10
3547H-1AA-502A	50	25	50	10
3547H-1AB-202A	50	25	50	10
3547H-1AC-102B	50	25	50	10
3547H-1AC-103B	50	25	50	10
3547H-1AC-203A	50	25	50	10
3547H-1AC-502A	50	25	50	10
3547H-1AC-502B	50	25	50	10
3547H-559-102Z	100	5	100	10
3547H-562-102A	100	25	100	10
3547H-578-102Z	100	5	100	10
3547H-582-103A	1000	25	210	10
3547S-1AA-102A	50	25	50	10
3547S-1AA-102B	50	25	50	10
3547S-1AA-103A	50	25	50	10
3547S-1AA-202A	50	25	50	10
3547S-1AA-203B	50	25	50	10

Part Number	Current MOQ	Mult	New MOQ	Mult
3547S-1AA-502A	50	25	50	10
3547S-1AB-202A	50	25	50	10
3547S-1AB-502A	50	25	50	10
3547S-1AC-102A	50	25	50	10
3547S-1AC-103B	50	25	50	10
3547S-1AC-201A	50	25	50	10
3547S-1AC-203B	50	25	50	10
3547S-1AC-503B	50	25	50	10
3547S-1AD-502B	50	25	50	10
3547S-1AG-103A	50	25	50	10
3547S-1BA-501A	50	25	50	10
3547S-1BB-103A	50	25	50	10
3547S-1BH-102A	50	25	50	10
3547S-545-103A	500	5	210	10
3547S-583-103A	500	5	210	10
3547S-589-503B	100	100	100	10
3547S-592-103A	500	25	210	10
3547S-82-503AT	25	25	25	10

Improved Packaging Material for Certain Bourns® Precision Potentiometers - Plastic Blister Trays

October 17, 2018

Page 5 of 10

Affected Part Numbers (Continued)

Part Number	Current MOQ	Mult	New MOQ	Mult
3548H-1AA-102A	50	25	50	10
3548H-1AA-102B	50	25	50	10
3548H-1AA-103A	50	25	50	10
3548H-1AA-103B	50	25	50	10
3548H-1AA-502A	50	25	50	10
3548H-1AB-302A	50	25	50	10
3548H-1AB-502A	50	25	50	10
3548H-1AB-502B	50	25	50	10
3548H-1AC-103A	50	25	50	10
3548H-1AC-103B	50	25	50	10
3548H-1BA-103B	50	25	50	10
3548H-551-102B	100	25	100	10
3548H-554-103A	100	25	100	10
3548H-556-103A	100	10	100	10
3548H-558-102Z	100	5	100	10
3548H-577-102Z	100	5	100	10
3548H-590-103B	50	25	50	10
3548H-602-103A	100	25	100	10
3548S-1AA-102A	50	25	50	10
3548S-1AA-102B	50	25	50	10
3548S-1AA-103A	50	25	50	10
3548S-1AA-202A	50	25	50	10
3548S-1AA-502A	50	25	50	10

Part Number	Current MOQ	Mult	New MOQ	Mult
3548S-1AA-503B	50	25	50	10
3548S-1AB-103A	50	25	50	10
3548S-1AB-302A	50	25	50	10
3548S-1AB-502A	50	25	50	10
3548S-1AC-102B	50	25	50	10
3548S-1AC-103A	50	25	50	10
3548S-1AC-103B	50	25	50	10
3548S-1AG-103A	50	25	50	10
3548S-1BA-102B	50	25	50	10
3548S-1BA-103A	50	25	50	10
3548S-1BA-103B	50	25	50	10
3548S-1BA-202A	50	25	50	10
3548S-1BA-502B	50	25	50	10
3548S-1BB-102B	50	25	50	10
3548S-1BD-503B	50	25	50	10
3548S-566-103A	500	5	210	10
3548S-569-102B	500	5	210	10
3548S-569-103B	500	5	210	10
3548S-584-103A	500	5	210	10
3548S-593-103A	500	5	210	10
3548S-82-503AT	25	5	25	10

Part Number	Current MOQ	Mult	New MOQ	Mult
3549H-1AA-102A	50	25	50	10
3549H-1AA-102B	50	25	50	10
3549H-1AA-103A	50	25	50	10
3549H-1AA-104A	50	25	50	10
3549H-1AA-202A	50	25	50	10
3549H-1AA-202B	50	25	50	10
3549H-1AA-203A	50	25	50	10
3549H-1AA-203B	50	25	50	10
3549H-1AA-502A	50	25	50	10
3549H-1AA-502B	50	25	50	10
3549H-1AA-503A	50	25	50	10
3549H-1AB-102A	50	25	50	10
3549H-1AB-302B	50	25	50	10
3549H-1AC-102B	50	25	50	10
3549H-1AC-103B	50	25	50	10
3549H-1AC-202B	50	25	50	10
3549H-1AC-502B	50	25	50	10
3549H-1AG-102A	50	25	50	10
3549H-1AG-502B	50	25	50	10
3549H-1BA-102A	50	25	50	10

Part Number	Current MOQ	Mult	New MOQ	Mult
3549H-1BA-102B	50	25	50	10
3549H-1BA-103A	50	25	50	10
3549H-1BA-103B	50	25	50	10
3549H-1BA-502B	50	25	50	10
3549H-1BB-103A	50	25	50	10
3549H-1BC-102A	50	25	50	10
3549H-1BC-103A	50	25	50	10
3549H-1BD-103B	50	25	50	10
3549H-1BG-102B	50	25	50	10
3549H-1BH-502B	50	25	50	10
3549H-501-102B	100	5	100	10
3549H-501-103B	100	5	100	10
3549H-501-202B	100	5	100	10
3549H-501-502B	100	5	100	10
3549H-502-502B	100	25	100	10
3549H-509-102A	100	25	100	10
3549H-509-103A	100	25	100	10
3549H-509-502A	100	25	100	10
3549H-510-103A	100	25	100	10
3549H-510-202A	100	25	100	10

Improved Packaging Material for Certain Bourns® Precision Potentiometers - Plastic Blister Trays

October 17, 2018

Page 6 of 10

Affected Part Numbers (Continued)

Part Number	Current MOQ	Mult	New MOQ	Mult
3549H-510-203A	100	25	100	10
3549H-525-102A	1500	25	210	10
3549H-526-102A	100	25	100	10
3549H-526-103A	100	25	100	10
3549H-526-103B	100	25	100	10
3549H-526-202A	100	25	100	10
3549H-526-502A	100	25	100	10
3549H-553-103A	100	5	100	10
3549H-557-102A	100	1	100	10
3549H-563-102B	100	25	100	10
3549H-564-102B	100	5	100	10
3549H-565-103A	100	5	100	10
3549H-575-102B	100	5	100	10
3549H-588-103A	50	25	50	10
3549H-595-103A	50	50	50	10
3549H-601-103B	250	25	210	10
3549S-1AA-101A	50	25	50	10
3549S-1AA-102A	50	25	50	10
3549S-1AA-102B	50	25	50	10
3549S-1AA-103A	50	25	50	10
3549S-1AA-103B	50	25	50	10
3549S-1AA-104A	50	25	50	10
3549S-1AA-104B	50	25	50	10
3549S-1AA-201A	50	25	50	10
3549S-1AA-202A	50	25	50	10
3549S-1AA-202B	50	25	50	10
3549S-1AA-203A	50	25	50	10
3549S-1AA-203B	50	25	50	10
3549S-1AA-501A	50	25	50	10
3549S-1AA-501B	50	25	50	10
3549S-1AA-502A	50	25	50	10
3549S-1AA-502B	50	25	50	10
3549S-1AA-503A	50	25	50	10
3549S-1AB-102B	50	25	50	10
3549S-1AB-103B	50	25	50	10
3549S-1AB-202A	50	25	50	10
3549S-1AB-203A	50	25	50	10
3549S-1AB-302B	50	25	50	10
3549S-1AB-501B	50	25	50	10
3549S-1AB-502A	50	25	50	10
3549S-1AB-502B	50	25	50	10
3549S-1AC-102B	50	25	50	10
3549S-1AC-103A	50	25	50	10

Part Number	Current MOQ	Mult	New MOQ	Mult
3549S-1AC-103B	50	25	50	10
3549S-1AC-202B	50	25	50	10
3549S-1AC-502B	50	25	50	10
3549S-1AC-503A	50	25	50	10
3549S-1AD-102A	50	25	50	10
3549S-1AD-103A	50	25	50	10
3549S-1AD-103B	50	25	50	10
3549S-1AG-102A	50	25	50	10
3549S-1AG-103A	50	25	50	10
3549S-1AG-104A	50	25	50	10
3549S-1AG-501A	50	25	50	10
3549S-1AG-502A	50	25	50	10
3549S-1BA-102B	50	25	50	10
3549S-1BA-103A	50	25	50	10
3549S-1BA-202A	50	25	50	10
3549S-1BA-502A	50	25	50	10
3549S-1BA-502B	50	25	50	10
3549S-1BB-102B	50	25	50	10
3549S-1BB-103B	50	25	50	10
3549S-1BB-502B	50	25	50	10
3549S-1BC-101A	50	25	50	10
3549S-1BC-102A	50	25	50	10
3549S-1BC-103B	50	25	50	10
3549S-1BD-103A	50	25	50	10
3549S-1BG-502B	50	25	50	10
3549S-1BH-203B	50	25	50	10
3549S-530-102A	100	5	100	10
3549S-530-103A	100	5	100	10
3549S-543-102A	100	5	100	10
3549S-543-103A	100	5	100	10
3549S-544-103A	100	5	100	10
3549S-561-103A	100	5	100	10
3549S-571-103AT	100	5	100	10
3549S-573-103A	100	5	100	10
3549S-579-501A	100	5	100	10
3549S-581-103B	500	25	210	10
3549S-585-103A	500	25	210	10
3549S-586-103A	100	25	100	10
3549S-591-103A	100	25	100	10
3549S-594-103A	500	25	210	10
3549S-603-102A	100	25	100	10
3549S-82-104AT	25	5	20	10
3549S-82-503AT	25	5	20	10

Improved Packaging Material for Certain Bourns® Precision Potentiometers - Plastic Blister Trays

October 17, 2018

Page 7 of 10

Affected Part Numbers (Continued)

Part Number	Current MOQ	Mult	New MOQ	Mult
3590P-1-102L	50	25	50	10
3590P-1-103L	50	25	50	10
3590P-1-104L	50	25	50	10
3590P-1-201L	50	25	50	10
3590P-1-502L	50	25	50	10
3590P-2-102L	50	25	50	10
3590P-2-103L	50	25	50	10
3590P-2-104L	50	25	50	10
3590P-2-201L	50	25	50	10
3590P-2-203L	50	25	50	10
3590P-2-502L	50	25	50	10
3590P-2-503L	50	25	50	10
3590P-4-103L	50	25	50	10
3590P-4-202L	50	25	50	10
3590P-4-203L	50	25	50	10
3590P-4-503L	50	25	50	10
3590S-1-102L	50	25	50	10
3590S-1-103L	50	25	50	10
3590S-1-104L	50	25	50	10
3590S-1-201	50	25	50	10
3590S-1-201L	50	25	50	10
3590S-1-202L	50	25	50	10
3590S-1-203L	50	25	50	10
3590S-1-501L	50	25	50	10
3590S-1-502L	50	25	50	10
3590S-1-503L	50	25	50	10
3590S-2-101L	50	25	50	10
3590S-2-102L	50	25	50	10
3590S-2-103L	50	25	50	10
3590S-2-104L	50	25	50	10
3590S-2-201L	50	25	50	10
3590S-2-202L	50	25	50	10
3590S-2-203L	50	25	50	10
3590S-2-252L	50	25	50	10
3590S-2-501L	50	25	50	10
3590S-2-502L	50	25	50	10
3590S-2-503L	50	25	50	10
3590S-3-102L	50	25	50	10
3590S-3-103L	50	25	50	10
3590S-3-502L	50	25	50	10
3590S-4-102L	50	25	50	10
3590S-4-103L	50	25	50	10
3590S-4-104L	50	25	50	10
3590S-4-201L	50	25	50	10
3590S-4-202L	50	25	50	10
3590S-4-203L	50	25	50	10

Part Number	Current MOQ	Mult	New MOQ	Mult
3590S-4-501L	50	25	50	10
3590S-4-502L	50	25	50	10
3590S-6-101L	50	25	50	10
3590S-6-102L	50	25	50	10
3590S-6-103L	50	25	50	10
3590S-6-104L	50	25	50	10
3590S-6-201L	50	25	50	10
3590S-6-202	50	25	50	10
3590S-6-202L	50	25	50	10
3590S-6-203L	50	25	50	10
3590S-6-501L	50	25	50	10
3590S-6-502L	50	25	50	10
3590S-6-503L	50	25	50	10
3590S-7-202L	50	5	50	10
3590S-8-102L	50	25	50	10
3590S-8-103L	50	25	50	10
3590S-8-202L	50	25	50	10
3590S-8-502L	50	25	50	10
3590P-291-501L	100	25	100	10
3590P-A69-103L	100	25	100	10
3590S-291-102L	100	25	100	10
3590S-291-103L	100	25	100	10
3590S-291-203L	100	25	100	10
3590S-291-502L	100	25	100	10
3590S-491-102L	100	5	100	10
3590S-491-103L	100	10	100	10
3590S-A07-103L	0	0	10	10
3590S-A10-104L	125	5	120	10
3590S-A17-103L	125	5	120	10
3590S-A17-104L	125	5	120	10
3590S-A17-503L	125	5	120	10
3590S-A26-102L	125	5	120	10
3590S-A26-103L	125	5	120	10
3590S-A26-104L	125	5	120	10
3590S-A26-201L	125	5	120	10
3590S-A26-202L	125	5	120	10
3590S-A26-203L	125	5	120	10
3590S-A26-501L	125	5	120	10
3590S-A26-502L	125	5	120	10
3590S-A26-503L	125	5	120	10
3590S-A28-103L	50	25	50	10
3590S-A31-103L	125	5	120	10
3590S-A32-303L	125	5	120	10
3590S-A33-702L	100	5	100	10
3590S-A35-603L	125	5	120	10
3590S-A37-502L	125	5	120	10

Improved Packaging Material for Certain Bourns® Precision Potentiometers - Plastic Blister Trays

October 17, 2018

Page 8 of 10

Affected Part Numbers (Continued)

Part Number	Current MOQ	Mult	New MOQ	Mult
3590S-A43-103L	125	5	120	10
3590S-A45-102L	125	5	120	10
3590S-A45-202L	125	5	120	10
3590S-A45-203L	125	5	120	10
3590S-A49-102L	125	5	120	10
3590S-A49-103L	125	5	120	10
3590S-A49-502L	125	5	120	10
3590S-A58-103L	1000	25	210	10
3590S-A64-102L	125	5	120	10
3590S-A66-103L	125	5	120	10
3590S-A67-103L	500	5	210	10
3590S-A68-103L	500	5	210	10
3590S-A70-101L	100	5	100	10
3590S-A70-102L	100	5	100	10
3590S-A70-103L	100	5	100	10
3590S-A70-104L	100	5	100	10

Part Number	Current MOQ	Mult	New MOQ	Mult
3590S-A70-202L	100	5	100	10
3590S-A70-502L	100	5	100	10
3590S-A70-503L	100	5	100	10
3590S-A72-103L	1000	125	210	10
3590S-A74-503L	1000	5	210	10
3590S-A75-103L	100	5	100	10
3590S-A76-103L	500	5	210	10
3590S-A77-103L	1600	100	210	10
3590S-A79-102L	5000	25	210	10
3590S-A79-103L	5000	25	210	10
3590S-A79-104L	5000	25	210	10
3590S-A79-202L	5000	25	210	10
3590S-A79-203L	5000	25	210	10
3590S-A79-502L	5000	25	210	10
3590S-BKX-503L	125	5	120	10

Part Number	Current MOQ	Mult	New MOQ	Mult
6534N-ZSB-103	100	5	100	10
6534S-1-102	50	25	50	10
6534S-1-103	50	25	50	10
6534S-1-203	50	25	50	10
6534S-1-502	50	25	50	10
6534S-1-503	50	25	50	10
6534S-563-502	100	10	100	10
6534S-BUS-103	50	5	50	10
6537S-1-102	50	25	50	10
6537S-1-103	50	25	50	10
6537S-1-202	50	25	50	10
6537S-1-203	50	25	50	10
6537S-1-502	50	25	50	10
6537S-413-103	0	0	10	10
6537S-414-102	100	1	100	10
6537S-416-103	100	5	100	10
6537S-416-502	100	5	100	10
6537S-416-502	100	5	100	10
6537S-421-103	100	5	100	10
6537S-421-502	100	5	100	10
6537S-48-202	100	5	100	10
6537S-48-502	100	5	100	10
6537S-BFM-502	0	0	210	10
6537S-BHR-502	0	0	210	10
6537S-BSM-112	50	5	50	10
6537S-BZZ-502	100	5	100	10
6537S-ZUZ-203	100	5	100	10

Part Number	Current MOQ	Mult	New MOQ	Mult
6538S-1-102	50	25	50	10
6538S-1-103	50	25	50	10
6538S-1-202	50	25	50	10
6538S-1-203	50	25	50	10
6538S-1-502	50	25	50	10
6538S-45-102	50	1	50	10
6538S-45-103	50	1	50	10
6538S-45-202	50	1	50	10
6538S-45-502	50	1	50	10
6538S-48-103	50	1	50	10
6538S-48-202	50	1	50	10
6538S-48-502	50	1	50	10
6538S-488-103	0	0	210	10
6538S-489-502	100	1	100	10
6538S-496-103	100	1	100	10
6538S-497-102	100	1	100	10
6538S-498-203	600	600	210	10
6538S-499-103	100	1	100	10
6538S-500-502	100	1	100	10
6538S-51-502	50	1	50	10
6539S-1-102	50	25	50	10
6539S-1-103	50	25	50	10
6539S-1-202	50	25	50	10
6539S-1-203	50	25	50	10
6539S-1-502	50	25	50	10
6539S-1-503	50	25	50	10
6539S-400-502	0	0	210	10

Improved Packaging Material for Certain Bourns® Precision Potentiometers - Plastic Blister Trays

October 17, 2018

Page 9 of 10

Affected Part Numbers (Continued)

Part Number	Current MOQ	Mult	New MOQ	Mult
65395-401-502	0	0	210	10
65395-48-502	0	0	210	10
65395-BUK-502	100	1	100	10
6630S0A-B28-R103	50	25	50	10
6630S0A-B28-R502	50	25	50	10
6630S0A-C28-R102	50	25	50	10
6630S0A-C28-R103	50	25	50	10
6630S0D-502-A103	50	25	50	10
6630S0D-503-Z502	50	5	50	10
6630S0D-B28-A202	50	25	50	10
6630S0D-B28-A203	50	25	50	10
6630S0D-B28-A502	50	25	50	10
6630S0D-B28-R102	50	25	50	10
6630S0D-B28-R103	50	25	50	10
6630S0D-B28-R203	50	25	50	10
6630S0D-B28-R502	50	25	50	10
6630S0D-C28-A102	50	25	50	10
6630S0D-C28-A103	50	25	50	10
6630S0D-C28-A502	50	25	50	10
6630S1A-508-R103	500	5	210	10
6630S1A-B28-A102	50	25	50	10
6630S1A-B28-R102	50	25	50	10
6630S1A-B28-R103	50	25	50	10
6630S1A-B28-R203	50	25	50	10
6630S1A-B28-R502	50	25	50	10
6630S1A-C28-A102	50	25	50	10
6630S1A-C28-A103	50	25	50	10
6630S1A-C28-R103	50	25	50	10
6630S1A-C28-R203	50	25	50	10
6630S1A-C28-R502	50	25	50	10
6630S1D-B28-A102	50	25	50	10
6630S1D-B28-A103	50	25	50	10
6630S1D-B28-A203	50	25	50	10
6630S1D-B28-A502	50	25	50	10
6630S1D-C28-A102	50	25	50	10
6630S1D-C28-A103	50	25	50	10
6630S1D-C28-A502	50	25	50	10
6630S1D-C28-R102	50	25	50	10
6630S1D-C28-R502	50	25	50	10
6637N-415-103	100	2	100	10
6637N-456-103	0	0	210	10
6637S-1-102	50	25	50	10
6637S-1-103	50	25	50	10
6637S-1-104	50	25	50	10
6637S-1-202	50	25	50	10
6637S-1-203	50	25	50	10

Part Number	Current MOQ	Mult	New MOQ	Mult
6637S-1-502	50	25	50	10
6637S-4-102	100	25	100	10
6637S-4-103	100	25	100	10
6637S-4-202	100	25	100	10
6637S-448-103	100	1	100	10
6637S-452-502	0	0	0	10
6637S-455-103	0	0	0	10
6637S-BJJ-2352	0	0	0	10
6637S-BYS-102	100	1	100	10
6638S-1-102	50	25	50	10
6638S-1-103	50	25	50	10
6638S-1-202	50	25	50	10
6638S-1-502	50	25	50	10
6638S-1-503	50	25	50	10
6638S-433-202	100	1	100	10
6638S-456-202	100	5	100	10
6638S-461-102	100	25	100	10
6638S-461-202	100	25	100	10
6638S-461-502	100	25	100	10
6638S-471-102	100	1	100	10
6638S-BYY-103	125	5	120	10
6639S-1-102	50	25	50	10
6639S-1-103	50	25	50	10
6639S-1-104	50	25	50	10
6639S-1-202	50	25	50	10
6639S-1-203	50	25	50	10
6639S-1-502	50	25	50	10
6639S-1-503	50	25	50	10
6639S-301-102	50	25	50	10
6639S-301-103	50	25	50	10
6639S-301-202	50	25	50	10
6639S-301-502	50	25	50	10
6639S-407-102	100	1	100	10
6639S-408-102	100	1	100	10
6639S-427-103	125	5	120	10
6639S-429-102	125	5	120	10
6639S-432-472	125	5	120	10
6639S-444-102	100	1	100	10
6639S-445-502	100	1	100	10
6639S-446-203	100	1	100	10
6639S-455-502	100	50	100	10
6639S-458-552	500	500	210	10
6639S-459-502	100	50	100	10
6639S-460-502	100	5	100	10
6639S-464-103	25	25	20	10
6639S-464-502	25	25	20	10

Improved Packaging Material for Certain Bourns® Precision Potentiometers - Plastic Blister Trays

October 17, 2018

Page 10 of 10

Affected Part Numbers (Continued)

Part Number	Current MOQ	Mult	New MOQ	Mult
6639S-472-102	100	5	100	10
6639S-474-103	100	5	100	10
6639S-478-502	100	5	100	10
6639S-481-103	100	5	100	10
6639S-486-102	100	5	100	10
6639S-488-102	100	5	100	10
6639S-490-472	100	25	100	10
6639S-492-103	100	5	100	10
6639S-493-502	100	5	100	10
6639S-494-103	100	10	100	10
6639S-495-203	100	5	100	10
6639S-496-102	100	5	100	10
6639S-500-502	100	5	100	10
6639S-501-102	500	25	210	10

Part Number	Current MOQ	Mult	New MOQ	Mult
6639S-502-502	100	5	100	10
6639S-507-503	100	1	100	10
6639S-509-502	100	25	100	10
6639S-510-502	500	100	210	10
6639S-513-502	500	50	210	10
6639S-514-502	500	25	210	10
6639S-95-102	100	5	100	10
6639S-95-502	50	5	100	10
6639S-BNC-203	50	5	100	10
6639S-BPY-103	100	1	100	10
6639S-BRY-502	100	5	100	10
6639S-BUY-602	100	5	100	10
6639S-DCD-502	125	5	120	10