



CUSTOMER OPERATIONS
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: M000801

DATE: 18-May-2015

PRODUCT DISCONTINUANCE NOTICE

| Notice Type | Maxim Part Number | Recommended Replacement | Last Order Date | Last Delivery Date | Reason |
|----------------------|-------------------|-------------------------|-----------------|--------------------|--|
| Lead-Free Conversion | 73M1903C-IM/F | N/A | 18-May-2015 | 18-May-2017 | Part is leaded. Request information on lead-free version |
| Lead-Free Conversion | 78P2352-IEL/F | N/A | 18-Nov-2015 | 17-Nov-2017 | Part is leaded, and a lead-free replacement exists |
| Lead-Free Conversion | 78Q2133-DIE | N/A | 18-May-2015 | 18-May-2017 | Part is leaded. Request information on lead-free version |
| Lead-Free Conversion | DS1804U-100/T&R | DS1804U-100+T&R | 18-Nov-2015 | 17-Nov-2017 | Part is leaded. Request information on lead-free version |
| Lead-Free Conversion | MAX9169ESE | MAX9169EUE+ | 18-Nov-2015 | 17-Nov-2017 | Part is leaded. Request information on lead-free version |
| Lead-Free Conversion | MAX924C/D | N/A | 18-Nov-2015 | 17-Nov-2017 | Part is leaded, and a lead-free replacement exists |
| Lead-Free Conversion | MXL1016CS8 | MAX913ESA+ | 18-Nov-2015 | 18-May-2017 | Part is leaded. Request information on lead-free version |
| Lead-Free Conversion | MXL1016MJ8 | MAX913EPA+ | 18-Nov-2015 | 18-May-2017 | Part is leaded, and a lead-free replacement exists |
| Discontinuance | MAX14715EWC+ | N/A | 18-Nov-2015 | 17-Nov-2017 | Part can no longer be manufactured |
| Discontinuance | MAX34462EVKIT# | MAX34463EVKIT# | 18-May-2015 | 18-May-2017 | EVKIT is No Longer Supported |
| Discontinuance | MAX34462EXQ+ | N/A | 18-Nov-2015 | 17-Nov-2017 | Part can no longer be manufactured |
| Discontinuance | MAX34462EXQ+T | N/A | 18-Nov-2015 | 17-Nov-2017 | Part can no longer be manufactured |
| Discontinuance | MAX414BCSD+ | MAX4472ESD+ | 18-May-2015 | 18-May-2017 | Part can no longer be manufactured |
| Discontinuance | MAX414BESD+ | MAX4472ESD+ | 18-May-2015 | 18-May-2017 | Part can no longer be manufactured |
| Discontinuance | MAX7306EVKIT+ | N/A | 18-May-2015 | 18-May-2015 | EVKIT is No Longer Supported |
| Discontinuance | MAX9096AXT+ | N/A | 18-May-2015 | 18-May-2017 | The part was not released |
| Discontinuance | MXL1016CS8+ | MAX913ESA+ | 18-Nov-2015 | 17-Nov-2017 | Part can no longer be manufactured |
| Discontinuance | MXL1016CS8+T | MAX913ESA+T | 18-Nov-2015 | 17-Nov-2017 | Part can no longer be manufactured |
| Discontinuance | VT212B-ADJ | N/A | 18-Nov-2015 | 17-Nov-2017 | Part can no longer be manufactured |
| Discontinuance | VT212BX-ADJ | N/A | 18-Nov-2015 | 17-Nov-2017 | Part can no longer be manufactured |

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Jun-2015