

<b>PCN Number:</b>	20160628003	<b>PCN Date:</b>	7/21/2016
<b>Title:</b>	Datasheet for TXB0304		
<b>Customer Contact:</b>	<a href="#">PCN Manager</a>	<b>Dept:</b>	Quality Services
<b>Change Type:</b>			
<input type="checkbox"/> Assembly Site	<input type="checkbox"/> Design	<input type="checkbox"/> Wafer Bump Site	
<input type="checkbox"/> Assembly Process	<input checked="" type="checkbox"/> Data Sheet	<input type="checkbox"/> Wafer Bump Material	
<input type="checkbox"/> Assembly Materials	<input type="checkbox"/> Part number change	<input type="checkbox"/> Wafer Bump Process	
<input type="checkbox"/> Mechanical Specification	<input type="checkbox"/> Test Site	<input type="checkbox"/> Wafer Fab Site	
<input type="checkbox"/> Packing/Shipping/Labeling	<input type="checkbox"/> Test Process	<input type="checkbox"/> Wafer Fab Materials	
		<input type="checkbox"/> Wafer Fab Process	

### Notification Details

#### Description of Change:

Texas Instruments Incorporated is announcing an information only notification.

The product datasheet(s) is being updated as summarized below.

The following change history provides further details.



**TXB0304**

SCES831F – SEPTEMBER 2011 – REVISED MAY 2016

Changes from Revision E (August 2014) to Revision F	Page
• Made changes to <i>Description</i> section.....	1
• Made changes to <i>Absolute Maximum Ratings, Recommended Operating Conditions<sup>(1)(2)</sup>, Switching Characteristics</i> and <i>Electrical Characteristics</i> tables.....	1

The datasheet number will be changing.

Device Family	Change From:	Change To:
TXB0304	SCES831E	<b>SCES831F</b>

These changes may be reviewed at the datasheet links provided.

<http://www.ti.com/product/TXB0304>

#### Reason for Change:

To more accurately reflect device characteristics.

#### Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):

No anticipated impact. This is a specification change announcement only. There are no changes to the actual device.

#### Changes to product identification resulting from this PCN:

None.

#### Product Affected:

TXB0304RSVR	TXB0304RUTR	TXBN0304RSVR	TXBN0304RUTR
-------------	-------------	--------------	--------------

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	<a href="mailto:PCNAmericasContact@list.ti.com">PCNAmericasContact@list.ti.com</a>
Europe	<a href="mailto:PCNEuropeContact@list.ti.com">PCNEuropeContact@list.ti.com</a>
Asia Pacific	<a href="mailto:PCNAsiaContact@list.ti.com">PCNAsiaContact@list.ti.com</a>
Japan	<a href="mailto:PCNJapanContact@list.ti.com">PCNJapanContact@list.ti.com</a>