

Issue date: March 15, 2020

PTN No.: 401800F

Masatoshi Shimojima
Division manager
Small Signal Devices Division
General Purpose Device Production HQ
ROHM Co., Ltd.

Notification of Product Discontinuance

Dear Valued Customer

This letter intends as a formal notification that ROHM Co., Ltd. is discontinuing the production of the following product. We acknowledge the obligation to promptly inform our customers of the intent to exit products to enable our customers the ability to prepare for alternatives and/or assist in our product portfolio renewal process.

It would be very appreciated if you could your reply by 4/30/2020

Your early reply in this regard would be very much appreciated.

Product category	Affected part number(s)	Suggested replacement product
Diode	See Below	See Below
<u>Reason for discontinuance</u> <ul style="list-style-type: none">• Deterioration of the machine.• Administrative expense increase by the quantity of order decrease.		
<u>Product discontinuance date</u> Last Time Buy : 4/30/2020		
<u>NOTE</u> If no reply is received by 4/30/2020, ROHM will assume acceptance of this EOL Notice.		

EOL PN	Suggested Replacement
DA227YFHT2R	1SS400SMFHT2R
DA227YT2R	1SS400SMT2R
EMZH6.8YT2R	Not Applicable
RB480Y-40FHT2R	RB520SM-40FHT2R
RB480Y-40GT2R	RB520SM-40T2R
RB480Y-40T2R	RB520SM-40T2R
RB480Y-90FHT2R	Not Applicable
RB480Y-90T2R	Not Applicable
RB480YFHT2R	RB520SM-30FHT2R
RB480YFJT2R	RB520SM-30T2R
RB480YFST2R	RB520SM-30T2R
RB480YGJT2R	RB520SM-30T2R
RB480YNPT2R	RB520SM-30T2R
RB480YT2R	RB520SM-30T2R
RB480YT4R	Not Applicable
RB481Y-40FHT2R	RB521SM-40FHT2R
RB481Y-40T2R	RB521SM-40T2R
RB481Y-90FHT2R	Not Applicable
RB481Y-90T2R	Not Applicable
RB481Y9HKT2R	RB521SM-30FHT2R
RB481YFHT2R	RB521SM-30FHT2R
RB481YFJT2R	RB521SM-30T2R
RB481YSPT2R	RB521SM-30T2R
RB481YT2R	RB521SM-30T2R
RB751Y-40T2R	RB751SM-40T2R
RB851Y7HMT2R	Not Applicable
RB851YGT2R	Not Applicable
RB851YGT2RB	Not Applicable
RB851YT2R	Not Applicable
RB851YXNT2R	Not Applicable
RB861Y9HKT2R	Not Applicable
RB861YT2R	Not Applicable
RB886Y9HKT2R	Not Applicable
RB886YGT2R	Not Applicable
RB886YT2R	Not Applicable