



CUSTOMER OPERATIONS
 160 RIO ROBLES
 SAN JOSE, CA 95134

PDN #: M000800

DATE: 22-Apr-2015

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Reactivation	MAX15090EVKIT#	N/A			Reactivation
Reactivation	MAX19794ETX+	MAX19791ETX+			Reactivation
Reactivation	MAX19794ETX+T	MAX19791ETX+T			Reactivation
Reactivation	MAX7365EWA70+T	N/A			Reactivation
Reactivation	MAX2769E/W-GB6	N/A			Reactivation
Reactivation	MAX7365EWA70+	N/A			Reactivation
Reactivation	MAX2769ETI+T	N/A			Reactivation
Reactivation	MAX15090EWI+	N/A			Reactivation
Reactivation	MAX15090EWI+TW	N/A			Reactivation
Reactivation	MAX9679AETG+T	N/A			Reactivation
Reactivation	MAX2769E/W-TGB6	N/A			Reactivation
Reactivation	DS1088CX-133+	N/A			Reactivation
Reactivation	MAX2769EVKIT+	N/A			Reactivation
Reactivation	MAX15090EWI+T	N/A			Reactivation
Reactivation	MAX2769ETI+	N/A			Reactivation
Reactivation	MAX9679AETG+	N/A			Reactivation
Reactivation	MAX2117EVKIT+	N/A			Reactivation
Reactivation	DS1088CX-133+T	N/A			Reactivation

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 23-May-2015