



Sensing and Control
1985 Douglas Drive North
Golden Valley, MN 55422
1-815-235-5500

December 4, 2013

< Customer FSE First Name> < Customer FSE Last Name>
< Cust Name>
<Customer Address (1st Line)>
< Customer City>, < Customer State Abbr> < Customer Zipcode>
< Customer Country Desc>

Dear < Customer FSE Last Name>,

RE: Announcing Notification of Replacement of Resin used in Certain Infrared Sensors

Several Honeywell Sensing and Control (S&C) infrared sensors are affected by the obsolescence of Udel P1700-BK1615 grade resin by our supplier. S&C has identified an alternative resin that is nearly identical to the obsolete resin in terms of form, fit and function.

As a result of this resin change, S&C has evaluated its infrared sensor portfolio and has determined those infrared sensors that we will continue to support, and those that we will make obsolete effective immediately due to no/low sales volume. See Table 1, starting on page 2, for a list of those products.

Action

Please inform Honeywell S&C by December 15, 2013 if you require validation/testing with the new resin.

For additional information, please contact:

- Product Marketing Specialist, Infrared: Pavitra Bandapati, Pavitra.Bandapati@honeywell.com, +1 763-954-5053
- Applications Engineer, Infrared: James Marple, james.marple@honeywell.com, +1 972-470-4264

Best regards,

Pavitra Bandapati

Pavitra Bandapati
Product Marketing Specialist, Magnetics

Table 1. Affected Listings

Infrared Sensors that Honeywell will Continue to Support	Infrared Sensors that will be made Obsolete, Effective Immediately
HOA6333-002	HOA6274-005
HOA6450-001	HOA6274-001
SPX4995-003	HOA6274-007
HOA6471-001	HOA6274-008
HOA6344-005	HOA6267-004
HOA6344-006	HOA6267-003
HOA1405-105	HOA6393-001
HOA1405-109	HOA6394-001
HOA1405-110	HOA6293-001
HOA1405-002	HOA6293-003
HOA1405-001	HOA6293-004
HOA1405-111	**End of list**
HOA1405-502	
HOA6444-001	
HOA6444-002	
HOA6444-003	
HOA6444-004	
HOA6489-004	
HOA6489-006	
HOA6507-006	
HOA6507-002	
HOA6507-004	
HOA6507-005	
HOA6507-040	
HOA6516-001	
HOA6521-001	
HOA6522-001	
HOA6540-001	
HOA6542-001	
HOA6546-001	
HOA0860-N51	
HOA6963-N51	
HOA6961-N51	
HOA6962-N51	
HOA6960-N51	
HOA0961-N51	
HOA0963-N51	
HOA0865-N51	
HOA0865-106	

HOA6962-T51	
HOA0961-T51	
HOA6985-T51	
HOA6983-T51	
HOA0860-T51	
HOA6960-T51	
HOA0963-T51	
HOA6984-T51	
HOA6981-T51	
HOA6982-T51	
HOA0880-T51	
HOA6980-T51	
HOA0865-T51	
HOA6961-T51	
HOA6963-T51	
HOA0882-101	
HOA0880-L51	
HOA6963-L51	
HOA0865-L51	
HOA6981-L51	
HOA0961-L51	
HOA6983-500	
HOA6984-L51	
HOA0880-P51	
HOA0865-P51	
HOA0963-P51	
HOA6985-P51	
HOA0961-P51	
HOA0860-P51	
HOA6984-P51	
HOA6981-P51	
HOA0961-N55	
HOA0861-N55	
HOA0860-N55	
HOA1961-055	
HOA6984-N55	
HOA0866-101	
HOA0880-N55	
HOA0865-N55	
HOA0866-N55	
HOA0963-N55	

HOA6961-N55	
HOA6960-N55	
HOA0862-N55	
HOA6982-T55	
HOA6984-T55	
HOA6981-T55	
HOA0881-T55	
HOA0862-T55	
HOA0963-T55	
HOA6983-T55	
HOA0867-T55	
HOA6241-002	
HOA0882-T55	
HOA0865-100	
HOA6984-501	
HOA0865-T55	
HOA0880-T55	
HOA0861-T55	
HOA6241-001	
HOA6962-T55	
HOA0961-T55	
HOA0866-T55	
HOA0860-T55	
HOA6960-T55	
HOA6980-T55	
HOA6241-003	
HOA0880-L55	
HOA0881-L55	
HOA6410-001	
HOA0867-L55	
HOA6983-L55	
HOA0865-L55	
HOA0882-L55	
HOA6981-L55	
HOA0865-P55	
HOA0866-P55	
HOA0860-P55	
HOA0867-P55	
HOA0861-P55	
HOA6980-P55	
SPX5115-001	

HOA1879-011	
HOA1879-012	
HOA1879-015	
HOA2003-001	
HOA1882-012	
HOA1882-011	
HOA1882-013	
HOA6970-N11	
HOA6970-500	
HOA0709-011	
HOA0708-011	
HOA0708-101	
HOA0709-102	
HOA0709-103	
HOA6299-003	
HOA6299-002	
HOA6461-002	
HOA6432-001	
HOA6461-001	
HOA6274-006	
HOA6432-001	
End of List	